




AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.


IR_3501.jpg

6/20/2025 3:12:24 AM



DC_3502.jpg

6/20/2025 3:12:24 AM



Comment: Significant air leakage is apparent at all four sides of the main Lobby Twisted Roof. While this air leakage is significantly it is indirectly causing the snow to melt off and slide off onto lower roof sections.

IR_3497.jpg

6/20/2025 3:11:52 AM



DC_3498.jpg


6/20/2025 3:11:52 AM






AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.


IR_3515.jpg 6/20/2025 3:19:16 AM




DC_3516.jpg 6/20/2025 3:19:16 AM



IR_3513.jpg 6/20/2025 3:17:40 AM




DC_3514.jpg 6/20/2025 3:17:40 AM





AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.

IR_3349.jpg 6/20/2025 2:24:05 AM




DC_3350.jpg 6/20/2025 2:24:05 AM




Comment: Several wall sections showed air leakage signatures during the walk through the of the building. These air leakage pathways are typical of building corners, fenestrations and entryways.

IR_3521.jpg 6/20/2025 3:21:55 AM



DC_3522.jpg 6/20/2025 3:21:55 AM





AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.


IR_3509.jpg

6/20/2025 3:15:59 AM



DC_3510.jpg

6/20/2025 3:15:59 AM



IR_3365.jpg

6/20/2025 2:31:49 AM



DC_3366.jpg

6/20/2025 2:31:49 AM





AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.

IR_3427.jpg

6/20/2025 2:45:11 AM



DC_3428.jpg


6/20/2025 2:45:11 AM



Comment: The lower roof sections along the north side of PCC2 were found to have normal uniform signatures with leakage present at the narrow roof connection to the main building and parapet corners of the of the lower roofs near column WF.

IR_3429.jpg

6/20/2025 2:45:34 AM



DC_3430.jpg

6/20/2025 2:45:34 AM






AK Native Primary Care Center Bldgs I,II, III
Roof IR Report 6-18-2025 & 6-20-2025
Thermographic Imaging of the ANPCC Roof for Moisture
Detection & Heat Loss.

IR_3455.jpg

6/20/2025 2:50:31 AM




DC_3456.jpg

6/20/2025 2:50:31 AM



IR_3453.jpg

6/20/2025 2:50:04 AM



DC_3454.jpg

6/20/2025 2:50:04 AM





ATI Services Company


703 Gradelle Ave

Fairbanks, Alaska 99709

(907) 460-7669 email: 1Leffel@protonmail.com

www.atiservices.org

Appendix A



ATI Services Company
Emmett Leffel ITC # 140923361
Phone: 907-460-7669, e-mail: 1leffel@protonmail.com



ATI Services Company

703 Gradelle Ave

Fairbanks, Alaska 99709

(907) 460-7669 email: 1Leffel@protonmail.com

www.atiservices.org

61.22 °N, 149.89 °W

Anchorage, AK Weather History

60° MERRILL FIELD STATION | CHANGE

TODAY

HOURLY

10-DAY

CALENDAR

HISTORY

WUNDERMAP

Daily

Weekly

Monthly

June

18

2025

View



ATI Services Company

Emmett Leffel ITC # 140923361

Phone: 907-460-7669, e-mail: 1leffel@protonmail.com



ATI Services Company

703 Grabelle Ave

Fairbanks, Alaska 99709

(907) 460-7669 email: 1Leffel@protonmail.com

www.atiservices.org

61.22 °N, 149.89 °W

Anchorage, AK Weather History

58° MERRILL FIELD STATION | CHANGE

TODAY

HOURLY

10-DAY

CALENDAR

HISTORY

WUNDERMAP

Daily

Weekly

Monthly

June

20

2025

View



ATI Services Company

Emmett Leffel ITC # 140923361

Phone: 907-460-7669, e-mail: 1leffel@protonmail.com

This page intentionally left blank