SECTION 09 9123 INTERIOR PAINTING

PART 1 GENERAL

1.01 SECTION INCLUDES

- A. Surface preparation.
- B. Field application of paints.
- C. Scope: Finish interior surfaces exposed to view
 - Prime surfaces to receive wall coverings.
- D. Do Not Paint or Finish the Following Items:
 - 1. Items indicated not in contract.
 - 2. Items indicated to remain unfinished.
 - 3. Fire rating labels, equipment serial number and capacity labels, bar code labels, and operating parts of equipment.

1.02 DEFINITIONS

A. Comply with ASTM D16 for interpretation of terms used in this section.

1.03 REFERENCE STANDARDS

- A. ASTM D16 Standard Terminology for Paint, Related Coatings, Materials, and Applications 2016
- B. MPI (APSM) Master Painters Institute Architectural Painting Specification Manual Current Edition.
- C. SSPC-SP 1 Solvent Cleaning 2015, with Editorial Revision (2016).

1.04 SUBMITTALS

- A. Product Data: Provide complete list of products to be used, with the following information for each:
 - 1. Manufacturer's name, product name and/or catalog number, and general product category (e.g., "alkyd ename!").
 - 2. MPI product number (e.g., MPI #47).
 - Cross-reference to specified paint system(s) product is to be used in; include description of each system.
 - 4. Manufacturer's installation instructions.
 - 5. Indicate VOC content.
- B. Samples: Submit one paper "draw down" samples, 8-1/2 by 11 inches in size, illustrating range of colors available for each finishing product specified.
 - 1. Where sheen is specified, submit samples in only that sheen.
 - 2. Where sheen is not specified, discuss sheen options with Owner before preparing samples, to eliminate sheens not required.
 - 3. Allow 3 days for approval process, after receipt of complete samples by Owner.
- C. Manufacturer's Instructions: Indicate special surface preparation procedures.
- D. Maintenance Materials: Furnish the following for Owner's use in maintenance of project.
 - Extra Paint and Finish Materials: 1 gallon of each color; from the same product run, store where directed.
 - 2. Label each container with color in addition to the manufacturer's label.

1.05 DELIVERY, STORAGE, AND HANDLING

A. Deliver products to site in sealed and labeled containers; inspect to verify acceptability.

20064.01 / SCF Dena A.Coy Paint	09 9123 - 1	Interior Painting
Refresh		

- B. Container Label: Include manufacturer's name, type of paint, brand name, lot number, brand code, coverage, surface preparation, drying time, cleanup requirements, color designation, and instructions for mixing and reducing.
- C. Paint Materials: Store at minimum ambient temperature of 45 degrees F and a maximum of 90 degrees F, in ventilated area, and as required by manufacturer's instructions.

1.06 FIELD CONDITIONS

- A. Do not apply materials when surface and ambient temperatures are outside the temperature ranges required by the paint product manufacturer.
- B. Follow manufacturer's recommended procedures for producing best results, including testing of substrates, moisture in substrates, and humidity and temperature limitations.
- C. Provide lighting level of 80 ft candles measured mid-height at substrate surface.

PART 2 PRODUCTS

2.01 MANUFACTURERS

- A. Provide paints and finishes from the same manufacturer to the greatest extent possible.
 - If a single manufacturer cannot provide specified products, minor exceptions will be permitted provided approval by Architect is obtained using the specified procedures for substitutions.
- B. Paints:
 - 1. Base Manufacturer: Sherman Williams.
- C. Primer Sealers: Same manufacturer as topcoats.

2.02 PAINTS AND FINISHES - GENERAL

- A. Paints and Finishes: Ready-mixed, unless intended to be a field-catalyzed paint.
 - 1. Provide paints and finishes of a soft paste consistency, capable of being readily and uniformly dispersed to a homogeneous coating, with good flow and brushing properties, and capable of drying or curing free of streaks or sags.
 - 2. Supply each paint material in quantity required to complete entire project's work from a single production run.
 - 3. Do not reduce, thin, or dilute paint or finishes or add materials unless such procedure is specifically described in manufacturer's product instructions.
- 3. Sheens: Provide the sheens specified; where sheen is not specified, sheen will be selected later by Architect from the manufacturer's full line.

2.03 PAINT SYSTEMS - INTERIOR

- Paint I-OP Interior Surfaces to be Painted, Unless Otherwise Indicated: Including gypsum board.
 - 1. One top coat and one coat primer (If required).
 - 2. Top Coat(s): High Performance Architectural Interior Latex; 139.
 - a. Products:
 - 1) Sherwin-Williams Pre-Catalyzed Waterbased Epoxy, Eg-Shel. (MPI #139)
 - 3. Top Coat Sheen:
 - a. Eggshell: MPI gloss level 3; use this sheen per schedule in Part 3.
 - 4. Primer: As recommended by top coat manufacturer for specific substrate.
 -) Sherwin-Williams B28w2600 Promar 200 Zero VOC Primer, (MPI #50)

2.04 PRIMERS

- A. Primers: Provide the following unless other primer is required or recommended by manufacturer of top coats.
 - 1. Interior Latex Primer Sealer; MPI #50.
 - a. Products:
 - 1) As recommended by the manufacturer for application.

20064.01 / SCF Dena A.Coy Paint	09 9123 - 2	Interior Painting
Refresh		

2.05 ACCESSORY MATERIALS

- A. Accessory Materials: Provide primers, sealers, cleaning agents, cleaning cloths, sanding materials, and clean-up materials as required for final completion of painted surfaces.
- B. Patching Material: Latex filler.
- C. Fastener Head Cover Material: Latex filler.

PART 3 EXECUTION

3.01 EXAMINATION

- A. Verify that surfaces are ready to receive work as instructed by the product manufacturer.
- B. Examine surfaces scheduled to be finished prior to commencement of work. Report any condition that may potentially affect proper application.
- C. Test shop-applied primer for compatibility with subsequent cover materials.

3.02 PREPARATION

- A. Clean surfaces thoroughly and correct defects prior to application.
- B. Prepare surfaces using the methods recommended by the manufacturer for achieving the best result for the substrate under the project conditions.
- C. Remove or mask surface appurtenances, including electrical plates, hardware, light fixture trim, escutcheons, and fittings, prior to preparing surfaces or finishing.
- D. Seal surfaces that might cause bleeding through or staining of topcoat.
- E. Gypsum Board: Fill minor defects with filler compound. Spot prime defects after repair.
- F. Ferrous Metal:
 - 1. Solvent clean according to SSPC-SP 1.
 - 2. Shop-Primed Surfaces: Sand and scrape to remove loose primer and rust. Feather edges to make touch-up patches inconspicuous. Clean surfaces with solvent. Prime bare steel surfaces. Re-prime entire shop-primed item.
 - 3. Remove rust, loose mill scale, and other foreign substances using methods recommended in writing by paint manufacturer.

3.03 APPLICATION

- A. Apply products in accordance with manufacturer's written instructions and recommendations in "MPI Architectural Painting Specification Manual".
- B. Do not apply finishes to surfaces that are not dry. Allow applied coats to dry before next coat is applied.
- C. Apply each coat to uniform appearance in thicknesses specified by manufacturer.
- D. Vacuum clean surfaces of loose particles with HEPA filtration. Use tack cloth to remove dust and particles just prior to applying the next coat, if required.
- E. Reinstall electrical cover plates, hardware, light fixture trim, escutcheons, and fittings removed prior to finishing.

3.04 FIELD QUALITY CONTROL

3.05 PROTECTION

- A. Protect finishes until completion of project.
- B. Touch-up damaged finishes after Substantial Completion.

20064.01 / SCF Dena A.Coy Paint	09 9123 - 3	Interior Painting
Refresh		

Southcentral Foundation 02/02/24 Dena A. Coy SCF24-1127

3.06 SCHEDULE

- A. P1, Sherwin Williams Armagnac SW 6354 Promar 200 HP Zero VOC I Eg-Shel B20W0195.
- B. P2, Sherwin Williams Downy SW 7002, Promar 200 HP Zero VOC I Eg-Shel B20W0195.
- C. P3, Sherwin Williams Snowbound SW 7004, 200 HP Zero VOC I Eg-Shel B20W0195.
- D. P3, Sherwin Williams Chrysanthemum SW 6347, 200 HP Zero VOC I Eg-Shel B20W0195.
- E. P4, Sherwin Williams Hearts of Palm SW 6415, 200 HP Zero VOC I Eg-Shel B20W0195.
- F. P5, Sherwin Williams Sundrew SW 7688, 200 HP Zero VOC I Eg-Shel B20W0195.
- G. P6, Sherwin Williams Moonmist SW9144, 200 HP Zero VOC I Eg-Shel B20W0195.
- H. P7, Sherwin Williams Cottage Cream SW 7678, 200 HP Zero VOC I Eg-Shel B20W0195.

END OF SECTION

20064.01 / SCF Dena A.Coy Paint	09 9123 - 4	Interior Painting
Refresh		

ProMar® 200

Zero V.O.C. Interior Latex Primer

B28W02600 White



CHARACTERISTICS

ProMar 200 Zero V.O.C. Interior Latex Primer is a professional quality, interior vinyl acrylic primer.

This primer has been designed for use with the ProMar Series Interior Latex topcoats providing a complete system.

For use on these interior surfaces:

- Wood
- Drywall
- Plaster
- Masonry
- Primed Metal
- Previously painted surfaces

White Color:

For best topcoat color development, use the recommended "P"shade primer. Check color before use.

400 sq.ft.per gallon Coverage:

@ 4.0 mils wet; 1.0 mils dry

Drying and recoat times are temperature, humidity, and film thickness dependent

Drying Time, @ 77°F, 50% RH:

Touch: 1 hour Recoat: 4 hour

Finish: 0-5 units @85°

Tinting: Requires ColorCast Ecotoner for tinting.

For best topcoat color development, use the recommended "P"-shade primer. If desired, up to 4 oz per gallon of ColorCast Ecotoner can be used to approximate the topcoat color. Check color before use.

White B28W02600

V.O.C. (less exempt solvents):

less than 50 grams per litre; .42 lbs. per gallon As per 40 CFR 59.406

Volume Solids: 26 ± 2% Weight Solids: 43 ± 2% Weight per Gallon: 10.77 lbs Flash Point: N.A. Vehicle Type: Vinyl acrylic Shelf Life: 36 months unopened

WVP Perms (US):

 135.65 ± 5.07 perm grains/(hr ft2 in Hg)

COMPLIANCE

As of 11/17/2021, Complies with: OTC Yes **OTC Phase II** Yes S.C.A.Q.M.D. Yes **CARB** Yes CARB SCM 2007 Yes **CARB SCM 2020** Yes Canada Yes LEED® v4 & v4.1 Emissions Yes LEED® v4 & v4.1 V.O.C. Yes **EPD-NSF® Certified** Yes **MIR-Product Lens Certified** Yes **MPI**®

APPLICATION

No reduction necessary.

Apply at temperatures above 50°F.

Use a nylon-polyester brush

Roller:

Use a nap synthetic cover,

For specific brushes and rollers, please refer to our Brush and Roller Guide on sherwinwilliams.com

Spray—Airless:

Pressure 2000 p.s.i. .017-.021 inch Tip

APPLICATION TIPS

When spot priming on some surfaces, a non-uniform appearance of the final coat may result, due to differences in holdout between primed and unprimed areas. To avoid this, prime the entire surface rather than spot priming.

For optimal performance, this primer must be topcoated with a latex, alkyd-oil, water based epoxy, or solvent based epoxy coating on architectural applications.

SPECIFICATIONS

Drywall:

Yes

1 coat ProMar 200 Zero V.O.C. Latex Primer 2 coats Of appropriate finishes

Previously Painted:

1 coat ProMar 200 Zero V.O.C. Latex Primer 1-2 coats Of appropriate finishes

SURFACE PREPARATION

WARNING! Removal of old paint by sanding, scraping or other means may generate dust or fumes that contain lead. Exposure to lead dust or fumes may cause brain damage or other adverse health effects, especially in children or pregnant women. Controlling exposure to lead or other hazardous substances requires the use of proper protective equipment, such as a properly fitted respirator (NIOSH approved) and proper containment and cleanup. For more information, call the National Lead Information Center at 1-800-424-LEAD (in US) or contact your local health authority.

Remove all surface contamination by washing with an appropriate cleaner, rinse thoroughly and allow to dry. Existing peeled or checked paint should be scraped and sanded to a sound surface. Glossy surfaces should be sanded dull. Stains from water, smoke, ink, pencil, grease, etc. should be sealed with the appropriate primer-sealer. Recognize that any surface preparation short of total removal of the old coating may compromise the service length of the system.

Caulking - Gaps between walls, ceilings, crown moldings, and other interior trim can be filled with the appropriate caulk after priming the surface.

Drywall - Fill cracks and nail holes with patching paste-spackle and sand smooth. Joint compounds must be cured and sanded smooth. Remove all sanding dust.

Masonry, Concrete, Cement, Block - All new surfaces must be cured according to the supplier's recommendations—usually about 30 days. Remove all form release and curing agents. Rough surfaces can be filled to provide a smooth surface. If painting cannot wait 30 days, allow the surface to cure 7 days and prime the surface with Loxon Concrete & Masonry Primer

Plaster - Bare plaster must be cured and hard. Textured, soft, porous, or powdery plaster should be treated with a solution of 1 pint household vinegar to 1 gallon of water. Repeat until the surface is hard, rinse with clear water and allow to dry.

SURFACE PREPARATION

Mildew - Prior to attempting to remove mildew, it is always recommended to test any cleaner on a small, inconspicuous area prior to use. Bleach and bleaching type cleaners may damage or discolor existing paint films. Bleach alternative cleaning solutions may be advised.

Mildew may be removed before painting by washing with a solution of 1 part liquid bleach and 3 parts water. Apply the solution and scrub the mildewed area. Allow the solution to remain on the surface for 10 minutes. Rinse thoroughly with water and allow the surface to dry before painting. Wear protective eyewear, waterproof gloves, and protective clothing. Quickly wash off any of the mixture that comes in contact with your skin. Do not add detergents or ammonia to the bleach-water solution.

CAUTIONS

For interior use only.

Protect from freezing.

Non-photochemically reactive.

Not for use under wallpaper.

Before using, carefully read **CAUTIONS** on label

CRYSTALLINE SILICA: Use only with adequate ventilation. To avoid overexposure, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches, or dizziness, increase fresh air, or wear respiratory protection (NIOSH approved) or leave the area. Adequate ventilation required when sanding or abrading the dried film. If adequate ventilation cannot be provided wear an approved particulate respirator (NIOSH approved). Follow respirator manufacturer's directions for respirator use. Avoid contact with eyes and skin. Wash hands after using. Keep container closed when not in use. Do not transfer contents to other containers for storage. FIRST AID: In case of eye contact, flush thoroughly with large amounts of water. Get medical attention if irritation persists. If swallowed, call Poison Control Center, hospital emergency room, or physician immediately. DELAYED EFFECTS FROM LONG TERM OVEREXPOSURE. Abrading or sanding of the dry film may release crystalline silica which has been shown to cause lung damage and cancer under long term exposure. WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. DO NOT TAKE INTERNALLY. KEEP OUT OF THE REACH OF CHILDREN.

HOTW 11/17/2021 B28W02600 32 00 FRC, SP

CLEANUP INFORMATION

Clean spills, spatters, hands and tools immediately after use with soap and warm water. After cleaning, flush spray equipment with compliant cleanup solvent to prevent rusting of the equipment. Follow manufacturer's safety recommendations when using solvents.

The information and recommendations set forth in this Product Data Sheet are based upon tests conducted by or on behalf of The Sherwin-Williams Company. Such information and recommendations set forth herein are subject to change and pertain to the product offered at the time of publication. Consult your Sherwin-Williams representative or visit www.paintdocs.com to obtain the most current version of the PDS and/or an SDS.